University of Windsor

Facility Services

NOTICE OF SERVICE INTERRUPTION/WORK FORM

Date of Request (yyyy/mm/dd): 2018-04-20 **Requester**: Rajeev Chawla

Start Date – End

Start Date (yyyy/mm/dd) 2018-04-23 Time (s) 2:30 pm
End Date (yyyy/mm/dd) 2018-04-25 Time (s) 5:00 pm

Notes Repair drain line in the ceiling space

Building(s) Affected:
1: Essex Hall EH **2:** Please Select
3: Please Sele **4:** Please Select

Areas/Rooms Affected: Hallway access near room 292

Service to be interrupted:
1: _____ **2:** _____
3: _____ **4:** _____

Description/Reason for Project:

To set up enclosure for asbestos type 2 removal and clean up of pipe insulation. Ceiling space also has sprayed fire proofing. To repair the leaking drain pipe in the ceiling space.

Contractor: R C White **Phone #:** _____

Contractor/Project Managers: Ted **Phone #:** 519-791-7782

Should you have any questions or concerns, please contact

Rajeev Chawla, Maintenance Manager; 519-253-3000 ext. 2854.

Notes:

Contractor to call up at ECC control room to have the air ventilation turned off before start of work and call again to have the air ventilation turned back on completion.

The following reference links are attached for your information:
http://www.ccohs.ca/oshanswers/chemicals/asbestos/whatis.html
https://www.pinchin.com/services/hazardous-building-materials/133
http://www.pshsa.ca/wp-content/uploads/2014/05/Asbestos-in-the-Education-Workplace.pdf
http://www1.uwindsor.ca/facilityservices/AsbestosInventory