University of Windsor

Facility Services

NOTICE OF SERVICE INTERRUPTION/WORK FORM

Date of Request (yyyy/mm/dd): 2023-06-09 **Requester**: Robert Fontanini

Start Date – End

Start Date (yyyy/mm/dd) 2023-06-13 Time (s) 7 am
End Date (yyyy/mm/dd) 2023-06-17 Time (s) 4:00 pm

Notes Partial ventilation system out of service

Building(s) Affected:
1: Leddy Library (East) Main Building LIB
2: Please Sele
3: Please Sele
4: Please Select

Areas/Rooms Affected:

Service to be interrupted:
1: Air Conditioning
2:
3:
4:

Description/Reason for Project:

The cooling coils in Leddy need to be replaced to provide consistent cooling The air handler will be shutdown during the day for work to occur and restarted at night to re-cool the building

Contractor: Haller Mechanical **Phone #:**

Contractor/Project Managers: Peter Ferrato **Phone #:** 226 345 1781

Should you have any questions or concerns, please contact

Rob Fontanini 2867

Notes:

The following reference links are attached for your information:
http://www.ccohs.ca/oshanswers/chemicals/asbestos/whatis.html
https://www.pinchin.com/services/hazardous-building-materials/133
http://www.pshsa.ca/wp-content/uploads/2014/05/Asbestos-in-the-Education-Workplace.pdf
http://www1.uwindsor.ca/facilityservices/AsbestosInventory