University of Windsor

Facility Services

NOTICE OF SERVICE INTERRUPTION/WORK FORM

Date of Request (yyyy/mm/dd): 2018-05-28 **Requester**: Kevin Francis

Start Date – End

Start Date (yyyy/mm/dd) 2018-05-28 Time (s) 6:00 am
End Date (yyyy/mm/dd) 2018-05-31 Time (s) 11:30 pm

Notes

Building(s) Affected:
1: Erie Hall ERIE
2: Please Select
3: Please Sele
4: Please Select

Areas/Rooms Affected: Lower level corridor CB-107, G140 (plus A, B, C & D), G141 and G142

Service to be interrupted:
1: access to these areas
2: lower level - air distribution
3:
4:

Description/Reason for Project:

A water leak has damaged some ceilings, walls and flooring in the noted areas. Access is restricted to this area due to overhead danger.

The mechanical unit for the lower level of Erie Hall has been turned off while the abatement takes place. The University's HMIS web site indicates that some asbestos containing materials will need to be removed during the clean-up. An abatement contractor and environmental consultant are on-site managing the clean-up.

Contractor: Elmara Construction **Phone #:** 519 737-1253

Contractor/Project Managers: Mike Leslie **Phone #:** 519 737-1624

Should you have any questions or concerns, please contact

Kevin Francis
Project Administrator
519 253-3000, ext 2077

Notes:

Note to ECC: We will require our in-house team to turn the mechanical unit back on once the clean-up is complete. The contractor will contact you when they are finished their work and the Environmental Consultant has given their approval.

The following reference links are attached for your information:
http://www.ccohs.ca/oshanswers/chemicals/asbestos/whatis.html
https://www.pinchin.com/services/hazardous-building-materials/133
http://www.pshsa.ca/wp-content/uploads/2014/05/Asbestos-in-the-Education-Workplace.pdf
http://www1.uwindsor.ca/facilityservices/AsbestosInventory