University of Windsor

Facility Services

NOTICE OF SERVICE INTERRUPTION/WORK FORM

Date of Request (yyyy/mm/dd): 2018-12-07 **Requester**: Mark Rudkin

Start Date – End

Start Date (yyyy/mm/dd) 2019-01-03 Time (s) 3:30pm
End Date (yyyy/mm/dd) 2018-01-03 Time (s) 11:30pm

Notes Chrysler Hall - CCTV Camera Installation (2) - Basement & 2nd Floor

Building(s) Affected:
1: Chrysler Hall North CHN **2:** Chrysler Hall South CHS
3: Please Sele **4:** Please Select

Areas/Rooms Affected: Corridors - 2nd floor - outside room 260 & Basement - outside room G126

Service to be interrupted:
1: HVAC **2:** Working in Corridors
3: **4:**

Description/Reason for Project:

Two CCTV cameras will be installed in corridors: (1) 2nd floor - outside room 260 & (1) Basement - outside room G126.
Type II Enclosures will be setup for abatement of asbestos containing ceiling tiles.
All necessary precautions will be taken, including the shutdown of HVAC units as needed.
There will be no interruption with access to the building or exiting in the event of an emergency.

Contractor: Aatel Communications / Vollmer **Phone #:** Aatel: 905-526-2383

Contractor/Project Managers: Dave Thomson / Mike Shaw **Phone #:** Vollmer: 519-966-6100

Should you have any questions or concerns, please contact

Mark Rudkin, Project Administrator - Facility Services, 519-253-3000 x 2168

Notes:

Installation and termination of CCTV cameras will be performed on Jan.7, 2019

The following reference links are attached for your information:
http://www.ccohs.ca/oshanswers/chemicals/asbestos/whatis.html
https://www.pinchin.com/services/hazardous-building-materials/133
http://www.pshsa.ca/wp-content/uploads/2014/05/Asbestos-in-the-Education-Workplace.pdf
http://www1.uwindsor.ca/facilityservices/AsbestosInventory